












	4P	3P
A	1	1
B	8	6
C	3	2
D	4	4
E	2	2




②




- 1) Levier de commande
2) Poussoir d'essai mécanique (DPX-IS 630D)
1) Operating handle
2) Push-to-trip button for mechanical checking (DPX-IS 630D)
1) Betätigungshebel
2) Prüftaste für mechanische Kontrolle (DPX-IS 630D)
1) Leva di comando
2) Tasto di prova meccanica (DPX-IS 630D)
1) Planca de accionamiento
2) Pulsador de prueba para la verificación mecánica (DPX-IS 630D)

DPX-IS 630D


③




④




⑤




⑤a




⑥

















⑥a











⑥b










24



ø5...8

